

Jacuzzi Hot Tubs

Temperature Sensor/Hi-Limit Sensor Resistance Chart

Protech J-200, J-300 and J-400 Series Hot Tubs

Fahrenheit (°F)	Celsius (°C)	Ohms (Ω)
59.0.....	15.....	48840
60.8.....	16.....	46200
62.6.....	17.....	44610
64.4.....	18.....	42630
66.2.....	19.....	40770
68.0.....	20.....	39000
69.8.....	21.....	37290
71.6.....	22.....	35400
73.4.....	23.....	34170
75.2.....	24.....	32700
77.0.....	25.....	30000
78.8.....	26.....	28740
80.6.....	27.....	27540
82.4.....	28.....	26400
84.2.....	29.....	25311
86.0.....	30.....	24270
87.8.....	31.....	23280
89.0.....	32.....	22329
91.4.....	33.....	21429
93.2.....	34.....	20541
95.0.....	35.....	19740
96.8.....	36.....	18960
98.6.....	37.....	18210
100.4.....	38.....	17490
102.2.....	39.....	16800
104.0.....	40.....	16149
105.8.....	41.....	15519
107.6.....	42.....	14919
109.4.....	43.....	14349
111.2.....	44.....	13800
113.0.....	45.....	13281